



ONE-UP BOND F Plus


1. Mixing A&B



2. Application (Rub for 10sec)



3. Light irradiation



Please carefully read the attached instruction before using ONE-UP BOND F Plus